

This report is prepared exclusively for **Client Name**
Inspected On: **01-21-2025**

Company Information

Home Inspections DMV, LLC
301-250-3711

contact@inspectionsdmv.com

www.inspectionsDMV.com

[Published Report](#)



Inspected By:

Heriberto Interiano, MD, D.C & VA State
License #MD 34937, VA 3380002208

The Scope and Purpose of a Home Inspection

Purchasing property involves risk

The purpose of a home inspection is to help reduce the risk associated with the purchase of a structure by providing a professional opinion about the overall condition of the structure. A home inspection is a limited visual inspection, and it cannot eliminate this risk. Some homes present more risks than others. We cannot control this, but we try to help educate you about what we don't know during the inspection process. This is more difficult to convey in a report and one of many reasons why we recommend you attend the inspection.

A home inspection is not an insurance policy.

This report does not substitute for or serve as a warranty or guarantee. Home warranties can be purchased separately from insuring firms that provide this service.

A home inspection is visual and not destructive.

The descriptions and observations in this report are based on a visual inspection of the structure. We inspect the aspects of the structure that can be viewed without dismantling, damaging, or disfiguring the structure and without moving furniture and interior furnishings. Areas that are concealed, hidden, or inaccessible to view are not covered by this inspection. Some systems cannot be tested during this inspection as testing risks damaging the building. For example, overflow drains on bathtubs are generally not tested because if they were found to be leaking, they could damage the finishes below. Our procedures involve non-invasive investigation and non-destructive testing, which will limit the scope of the inspection.

This is not an inspection for code compliance.

This inspection and report are not intended for city / local code compliance. During the construction, process structures are inspected for code compliance by municipal inspectors. Framing is open at this time, and conditions can be fully viewed. Framing is not open during inspections of finished homes, limiting the inspection. All houses fall out of code compliance shortly after they are built, as the codes continually change. National codes are augmented at least every three years for all disciplines. Municipalities can adopt and phase in sections of the codes on their timetables. There are generally no requirements to bring older homes into compliance unless substantial renovation is being done.

This is just our opinion.

Construction techniques and standards vary. There is no one way to build a house or install a system in a house. The observations in this report are the opinions of the home inspector. Other inspectors and contractors are likely to have some differing opinions. You are welcome to seek opinions from other professionals.

The scope of this inspection

This inspection will include the following systems: exterior, roof, structure, drainage, foundation, attic, interior, plumbing, electrical, and heating. The evaluation will be based on limited observations that are primarily visual and non-invasive. This inspection and report are not intended to be technically exhaustive.

Your expectations

The overall goal of a home inspection is to help ensure that your expectations are appropriate for the house

you are proposing to buy. To this end, we assist with the discovery by showing and documenting observations during the home inspection. This should not be mistaken for a technically exhaustive inspection designed to uncover every defect in a building. Such inspections are available, but they are generally cost-prohibitive to most homebuyers.

Your participation is requested.

Your presence is requested during this inspection. A written report will not substitute for all the possible information that can be conveyed verbally by a shared visual observation of the conditions of the property.

How to Read This Report

Getting the Information to You

This report is designed to deliver important and technical information in a way that is easy for anyone to access and understand. If you are in a hurry, you can take a quick look at our ["Summary Page"](#) and quickly get the critical information for important decision-making. However, we strongly recommend that you take the time to read the full [Report](#), which includes digital photographs, captions, diagrams, descriptions, videos, and hot links to additional information.

The best way to get the layers of information presented in this report is to read your report online, which will allow you to expand your learning about your house. You will notice some words or series of words highlighted in blue and underlined – clicking on these will provide you with additional information.

This report can also be printed to a PDF file and printed on paper as desired.

Chapters and Sections

This report is divided into chapters that parcel the home into logical inspection components. Each chapter is broken into sections that relate to a specific system or component of the home. You can navigate between chapters with the click of a button on the left-side margin.

Most sections will contain some descriptive information in black font. Observation narrative, done in colored boxes, will be included if a system or component is found to be significantly deficient in some way or if we wish to provide helpful additional information about the system or the scope of our inspection. If a system or component of the home was deemed to be in satisfactory or serviceable condition, there might be no narrative observation comments in that section, and it may simply say "tested" or "inspected."

Observation Labels

All narrative observations are colored, numbered, and labeled to help you find, refer to, and understand the severity of the observation. Observation colors and labels used in this report are:

 **Major Concern:** Repair items that may cost significant money to correct now or in the near future, or items that require immediate attention to prevent additional damage or eliminate safety hazards.

 **Repair:** Repair and maintenance items noted during inspection. Please note that

some repair items can be expensive to correct such as re-finishing hardwood floors, but are considered simply repair items due to their cosmetic nature.

 **Recommended Maintenance:** These are repair items that should be considered "routine home ownership items," such as servicing the furnace, cleaning the gutters or changing the air filters in the furnace.

 **Due Diligence:** Observation such as a buried oil tank that may require further investigation to determine the severity and / or urgency of repair.

 **Monitor:** Items that should be watched to see if correction may be needed in the future.

 **Inspection Notes:** Aside information and /or comments elaborating on descriptions of systems in the home that the inspector might find useful to purchase decisions or home ownership. .

 **Limitations:** Conditions present at the time of inspection which limited the scope of this visual inspection

Summary Page

The Summary Page is designed as a bulleted overview of all the observations noted during the inspection. This helpful overview is not a substitute for reading the entire inspection report. The entire report must be read to get a complete understanding of this inspection report, as the Summary Page does not include photographs or photo captions.

Moisture Meter Testing

Where moisture meter testing is indicated in this report, a Extech MO260 Moisture Meter was used.

Summary

Major Concerns

No major concerns were noted during this visual inspection.

Repairs

G1-3 Grounds - Driveways/Walkways/Flatwork: TRIP HAZARD IN WALKWAY

The front walkway flatwork has settled creating a trip hazard. Hire a qualified general contractor to repair to eliminate trip hazard and ensure a reliable walking surface.

G1-4 Grounds - Fences: FENCE HAS BEEN CHAINED WITH LOCK

The rear fence gate has been closed with a chain and lock. Request key from sellers and test as needed.

E-2 Exterior - Siding and Trim: EXTERIOR ROT REPAIRS NEEDED

Localized rot repairs are needed to the exterior trim.

Recommendation

Hire a licensed general contractor to further evaluate and repair the exterior siding system. Repair and replace all damaged and decaying exterior wood as needed.

- Please note that this condition can indicate additional concealed damage/areas that is not visible to inspection.

E-3 Exterior - Siding and Trim: SIDING MAINTENANCE NEEDED

Localized caulking repairs are needed to the exterior of the building. This is common recommended maintenance between complete exterior paint jobs to ensure that the more exposed areas continue to perform reliably.

Recommendation

Implement painting and/or caulking repairs as recommended by a qualified contractor.

RCG-1 Roof, Chimney and Gutters - Roof Materials: MISALIGNED SHINGLES/ KICKOUT FLASHING MISSING

The lower right corner of the roof shows misaligned shingles, which could lead to water runoff issues and increase the risk of water intrusion. Additionally, kickout flashing is needed to direct water into the gutter and prevent damage to the siding/fascia. A professional roofing contractor should assess and address these issues to ensure proper function and durability.

FSD-2 Fuel Storage and Distribution - Gas, Propane and Oil Piping: IMPROPER USE OF FLEXIBLE GAS CONNECTORS

Flexible gas connectors should not run through the walls of appliances. Use rigid steel pipe only. Have this further evaluated and repaired by a qualified plumber or gas appliance technician.

EDF-1 Electric Distribution and Finish - Receptacles and Fixtures: INOPERATIVE LIGHTS

Inoperative lights were found in the basement. Have all inoperative lights further investigated and

repaired as needed. If a new bulb does not correct the problem, consult with a licensed electrical contractor.

 EDF-2 Electric Distribution and Finish - Receptacles and Fixtures: GFCI PROTECTED DEVICE DID NOT TRIP

The GFCI protected receptacle in the kitchen did not respond to testing and may be defective - it did not trip when tested. Have this receptacle repaired or replaced as needed.

 HCFV-3 Heating, Cooling, Fireplaces and Ventilation - Gas Fireplaces: GAS LOG FIREPLACE SHUT OFF AND IN NEED OF SERVICE

The gas log fireplace was shut off at the time of inspection. I do not like to light these when they are shut off as I do not know why they were shut off and there could be a safety reason. Also, glass pane is foggy. I recommend having this gas log fireplace clean and serviced by a qualified contractor and made operable as needed.

 I-2 Interior - Interior Doors: DOORS NOT LATCHING

The closet doors to the entrance foyer closet are not latching correctly and requires adjustment so the door latches closed.

 I-3 Interior - Windows: WINDOW REPAIRS/REPLACEMENT NEEDED

All of the windows in this building are original windows that require maintenance and/or replacement. You need to decide how you want to approach the windows in this building, as they are generally older and do not comply with modern standards for energy efficiency.. Existing windows that have character are often worth preserving and restoring, whereas windows that are in worse condition and have less character may be good candidates for replacement. The windows are in poor condition for age and type.

Examples of observations noted during the inspection include:

- Some windows in the home are not operating and may be painted/sealed shut.
- Missing window hardware was noted
- Condensation noted
- Many of the windows are single pane glass - these older windows do not comply with modern energy efficiency standards

 I-4 Interior - Windows: LOST SEAL / FAILED INSULATED GLASS UNIT

The exterior front right side window were presenting with a cloudy appearance. Often referred to as a, "lost seal," the cloudy appearance cannot be cleaned. Affected glass typically requires glazing repair or replacement.

Recommendation

Hire a glass replacement company to further evaluate the windows and glass here and replace/update all insulated glass units with lost seals.



- This is a common occurrence in insulated glass, especially as they age and on sun-exposed sides of the building.

 K-3 Kitchen - Cabinets and Countertops: CABINET DRAWER IN CONFLICT

A kitchen cabinet drawer adjustment is needed for proper operation of the kitchen cabinet as is in

conflict with the dishwasher.

LF-1 Laundry Facilities - Dryer: SCREENED DRYER EXHAUST VENT COVER

The [dryer exhaust duct](#) termination at the exterior of the building is covered with a screen. This is a potential safety hazard that could block lint and cause a fire. Replace this vent cover with a cover that has a backdraft damper.

B-2 Bathrooms - Sinks and Cabinets: SLOW SINK DRAIN

A slow drain was noted at the basement bath sink. Repair as needed so the drain keeps up with the fixture supply.

- This often involves just cleaning out the trap.

B-3 Bathrooms - Bathtub / Shower: SLOW TUB DRAIN

The main bath bathtub drain is slow and appears to be obstructed. Repair as needed for reliable drainage.

A-2 Attic - Attic Insulation: BAFFLES NOT INSTALLED

Cardboard baffles have not been installed in the rafters near the eaves in the attic. This has allowed the fiberglass batt insulation to block ventilation from the soffit. This can inhibit proper ventilation of this roof cavity and can lead to heat build-up and seasonal moisture problems. It is recommend removing insulation away from the roof decking in these areas as is possible - this will be difficult work due to the tight space restrictions. Where possible baffles should be added though this could be difficult at this point.

A-3 Attic - Attic Insulation: ATTIC INSULATION ADJUSTEMENT RECOMMENDED

Localized tune-up repairs are needed to the attic insulation to ensure reliable performance. During inspection the following observations were noted:



- Blown in insulation has been disturbed by contractors or prior attic access

Recommended Maintenance

G1-2 Grounds - Drainage and Site: DOWNSPOUTS DISCHARGE NEAR FOUNDATION

Downspouts are discharging adjacent to the foundation. This can cause foundation settlement or basement moisture problems. Make sure all downspouts discharge into a proper tight-line system that diverts water at least 5 feet away from the foundation.

HCFV-2 Heating, Cooling, Fireplaces and Ventilation - Heating Systems: SERVICE THE HEATING SYSTEM

Annual servicing of gas forced air furnaces is recommended for safe and reliable heat. I could not find recent service records on the furnace. A servicing is recommended if one has not been done in the last year. The furnace was tested during the inspection and was operational.

Due Diligence Items

FSD-1 Fuel Storage and Distribution - Gas, Propane and Oil Piping: NO CSST BONDING FOUND

The 2009 edition of NFPA 54, National Fuel Gas Code, includes new requirements for special bonding for CSST gas piping systems to the grounding conductor of the building's electrical system to reduce the possibility of damage by lightning strikes by reducing the electrical potential between metallic objects and building systems, including gas distribution. I was unable to locate a bonding connection for the CSST during the inspection today. Have this further evaluated and repaired as recommended by a qualified CSST installer.



- It is possible that bonding is present and was simply not found
- This building pre-dates requirements for bonding so it is more likely the gas piping was never bonded.

P-1 Plumbing - Water Meter: NO WATER METER FOUND

No water meter was found. This house seems to be on a public water system, which should have a metering device. Inquire with the seller or the utility as needed to locate the water meter.

P-2 Plumbing - Waste Pipe and Discharge: VIDEO SEWER SCOPE RECOMMENDED

An evaluation of the sewer line below the ground is beyond the scope of this inspection. A sewer scope is recommended to further evaluate the sewer line and the below ground connections between the house and the municipal sewer line as these are not visible to inspection. Sewer scopes are done using video cameras and can show the materials, condition and reliability of the sewer line. If a video scope has not been done recently, I recommend having a sewer scope performed.

K-6 Kitchen - Refrigerators: REFRIGERATOR FILTER NOTED

The refrigerator water / ice system seems to employ a filter. Inquire with the seller for additional information regarding replacement schedule and the types of filters needed.

Items for Monitoring

A-1 Attic - Roof Framing and Sheathing: OLD STAINED NOTED

A stain was observed on the FRT plywood around the chimney flue, indicating a past moisture issue. No active moisture was detected on the insulation, suggesting the issue has been resolved. It is recommended to inspect the chimney flashing and monitor the area periodically to ensure no recurrence.



The Complete Report

General Comments.....	p. 13
Building Characteristics, Conditions and Limitations	p. 13
Grounds.....	p. 14
General Grounds Photos.....	p. 14
Address Identification	p. 14
Drainage and Site.....	p. 14
Window and Stairwells	p. 15
Driveways/Walkways/Flatwork.....	p. 15
Grounds, Trees and Vegetation.....	p. 15
Exterior Stairs.....	p. 15
Retaining Walls	p. 15
Fences.....	p. 16
Outbuildings, Trellises, Storage Sheds, Barns.....	p. 16
Exterior	p. 16
Exterior Elevations	p. 16
Siding and Trim.....	p. 17
Exterior Vent and Exhaust Terminations.....	p. 18
Eaves	p. 18
Exterior Doors.....	p. 18
Exterior Window Frames	p. 18
Decks, Porches and Balconies.....	p. 18
Wood Decks Porches and Balconies.....	p. 18
Concrete Decks, Stoops, Landings and Porches.....	p. 19
Water-Resistant Decks and Balconies.....	p. 19
Roof, Chimney and Gutters	p. 19
Roof Materials	p. 19
Chimneys	p. 20
Skylights	p. 21
Gutters and Downspouts.....	p. 21
Exterior Roofing / Framing	p. 21
Fuel Storage and Distribution.....	p. 21
Gas Meter	p. 21
Gas, Propane and Oil Piping	p. 21

Electric Servicep. 22

Electric Service Voltage Tested p. 22

Electric Service..... p. 22

Electric Service Equipment..... p. 23

Generator Equipment p. 24

Appliance Disconnects..... p. 24

Electrical Grounding System..... p. 25

Electrical Bonding System..... p. 25

Electric Distribution and Finishp. 25

Branch Wiring..... p. 25

Receptacles and Fixtures p. 25

Smoke and Carbon Monoxide Alarm Systems p. 26

Ceiling Fansp. 27

Heating, Cooling, Fireplaces and Ventilation p. 28

Heating and Cooling System Overview..... p. 28

Heating Systems..... p. 28

Vents and Flues p. 29

Air Filters p. 30

Heating and Cooling Distribution Systems..... p. 30

Heat Pumps and Cooling Systems..... p. 31

Mechanical Ventilation Systems p. 32

Gas Fireplaces..... p. 32

Solid Fuel Fireplaces p. 33

Plumbingp. 33

Water Meter p. 33

Water Service Supply..... p. 33

Distribution Pipe p. 34

Waste Pipe and Discharge..... p. 35

Exterior Hose Bibs p. 35

Additional Sinks..... p. 36

Sump Pumps and Drains..... p. 36

Sewage Ejector Pumps..... p. 36

Water Heaters p. 36

Water Heater p. 36

Water Temperature..... p. 38

Interior p. 38

General Interior Photos p. 38

Floors and Floor Materials..... p. 40

Walls, Ceilings, Trim, Hallways and Closets p. 40

Wall Insulation and Air Bypass p. 40

Interior Stairs and Railings..... p. 40

Interior Doors..... p. 40

Windows..... p. 41

Kitchenp. 42

General Kitchen Photos p. 42

Sinks and Faucets p. 43

Cabinets and Countertops p. 43

Disposers p. 44

Dishwasher p. 44

Ventilation Method p. 44

Ranges, Ovens and Cooktops..... p. 44

Refrigerators..... p. 44

General Kitchen Condition p. 45

Laundry Facilities.....p. 45

Washer p. 45

Dryer p. 45

Laundry Sinks..... p. 47

Bathrooms..... p. 47

General Bathroom Photos..... p. 47

Sinks and Cabinets p. 47

Toilet..... p. 48

Bathtub / Shower..... p. 48

Bathroom Ventilation p. 48

General Bath p. 48

Attic p. 49

Attic Access..... p. 49

Attic Pulldown Ladders..... p. 49

Roof Framing and Sheathing p. 49

Fire Separation and Fire Blocking..... p. 50

Attic Insulation p. 50

Attic Fan Exhaust Vents..... p. 51

Attic and Roof Cavity Ventilation p. 51

Structure and Basement.....p. 52

 Foundation p. 52

 Floor, Wall and Ceiling Framing p. 52

 Basement p. 52

 Basement Moisture p. 52

Checking Out Procedure.....p. 53

 Check Out List p. 53

General Comments

Building Characteristics, Conditions and Limitations

Style of Home: Town home

Type of Building : Townhome

Townhouse Inspection: This inspection consists predominantly of an interior viewing of the inspected unit and a partial visual inspection of other areas of the perimeter of the structure - the roof, the grounds and the common areas that are available and open for observation. Only this unit was open to inspection, so there was no attention given to any adjacent units or other units in the structure. Regarding zero lot line townhouse construction, responsibilities for maintenance and repairs falls substantially on the individual owner, although there are sections of the structure that will need cooperative efforts for repair, such as roofs, common exterior walls, common exterior grounds etc. For specific responsibilities though, gaining information from the condominium association's agreement is recommended to determine the actual responsibilities of the new occupant and how it may be shared with the group. It is highly recommended that the association's building records and minutes be examined to determine whether there have been issues in the past at other units that might indicate a more substantial issue than what might be observed at the inspected unit, or that might require a general assessment. Occasionally, repairs that are planned to be undertaken at a building complex can require a substantial outlay of funds that may not be covered in the available monetary accounts of the building association. This might involve an assessment to each individual occupant. I would recommend gaining any information possible from the association regarding any planned repairs and the availability of funds to cover these situations, so as not to be surprised by a planned or special assessment.

Approximate Square Footage: 1400

The approximate square footage listed here is listed as a courtesy and is based off of public records and disclosure. An evaluation of square footage of the buildings and property lines is beyond the scope of this inspection.

Approximate Year of Original Construction: 1996

Attending the Inspection: Client's representative, Buyer

Occupancy: Occupied

Animals Present: No

Weather during the inspection: Cloudy, Ice

Please note that snow and ice will limit the scope of the inspection. Typically, a visual inspection of

the roof and grounds on the outside of the house is severely limited when snow and ice are present.

Approximate temperature during the inspection: Below 32[F]

Ground/Soil surface conditions: Snow-covered, Frozen

For the Purposes of This Report, the Front Door Faces: East

⚠ Limitations: This home was occupied at the time of the inspection. Inspection of occupied homes presents some challenges as occupant belongings can obstruct visual inspection of and access to parts of the building. We do our best during inspection to work around belongings to discover as much as possible about the house without moving or damaging personal property, however, the presence of personal items does limit the inspection.

Grounds

General Grounds Photos



Address Identification

Address Identification: Address Numbers Present and Well Displayed

Drainage and Site

Clearance to Grade: Standard

Downspout Discharge: Above and below grade, Next to Foundation, Corrugated Storm Drains

Site Description: Moderate slope

🔧 (G1-2) Recommended Maintenance:
DOWNSPOUTS DISCHARGE NEAR FOUNDATION

Downspouts are discharging adjacent to the foundation. This can cause foundation settlement or basement moisture problems. Make sure all downspouts discharge into a proper tight-line system that diverts water at least 5 feet away from the foundation.



Window and Stairwells

None Noted

Driveways/Walkways/Flatwork

Driveway: None noted

Walkways: Concrete

Patios: None noted

🔧 (G1-3) Repair:
TRIP HAZARD IN WALKWAY

The front walkway flatwork has settled creating a trip hazard. Hire a qualified general contractor to repair to eliminate trip hazard and ensure a reliable walking surface.



Grounds, Trees and Vegetation

Trees/Vegetation too near building: No

Exterior Stairs

Exterior Stairs: Simple landing noted

Retaining Walls

Retaining Wall Material: None Noted

Fences

Exterior Fencing: Present

The property has a fencing system in place. Inspection and evaluation of fencing is beyond the scope of a home inspection. If the fencing system is important for your use of this property, I recommended a self-examination to see how it will meet your needs. I may make cursory comments about fencing as a courtesy.

🔧 (G1-4) Repair:

FENCE HAS BEEN CHAINED WITH LOCK

The rear fence gate has been closed with a chain and lock.
Request key from sellers and test as needed.



Outbuildings, Trellises, Storage Sheds, Barns

None noted

Exterior

Exterior Elevations





Siding and Trim

Trim Material: Wood

Siding Material: Aluminum

🔧 (E-2) Repair: **EXTERIOR ROT REPAIRS NEEDED**

Localized rot repairs are needed to the exterior trim.

Recommendation

Hire a licensed general contractor to further evaluate and repair the exterior siding system. Repair and replace all damaged and decaying exterior wood as needed.

- Please note that this condition can indicate additional concealed damage/areas that is not visible to inspection.



Wood decay in fascia material



Wood decay in fascia material



Wood rot close to the downspout

🔧 (E-3) Repair: **SIDING MAINTENANCE NEEDED**

Localized caulking repairs are needed to the exterior of the building. This is common recommended maintenance between complete exterior paint jobs to ensure that the more exposed areas continue to preform reliably.

Recommendation

Implement painting and/or caulking repairs as recommended by a qualified contractor.



Exterior Vent and Exhaust Terminations

Exterior Siding and Vent Terminations: Present

Eaves

Aluminum

Exterior Doors

Exterior Door Styles: Solid core, Sliding glass

Exterior Window Frames

Window Frames: Wood, Vinyl

Decks, Porches and Balconies

Wood Decks Porches and Balconies

Present

To see a prescriptive guide for residential wood deck construction click [this link](#):

Structure: Not visible

Ledger Board: Standard

Guardrail: Standard

Decking Material: Hardwood

Posts, Beams and Footings: Inspected

Overall pictures of deck



Concrete Decks, Stoops, Landings and Porches

Concrete Features: Concrete entry

Water-Resistant Decks and Balconies

Water Proof Surfaces: None Noted

Roof, Chimney and Gutters

Roof Materials

Method of Roof Inspection: Viewed with a drone

Please note that the roof was too tall to access by ladder and walk safely. A drone was used to try and get some information about the roof. This is not as good an inspection as walking the roof but is the best and safest option, given limited access. Any relevant photos or videos will be included in this report.

Roof Style: Gable

Flashings, Valleys and Penetrations: Present and Visually Standard

Roof flashings are used to keep a roofing system waterproof where the roofing material starts, stops, changes direction, or is penetrated. During the inspection, we look for standard flashing techniques that could be considered normal or standard in our region. Damaged, incomplete or non-standard flashings can be a sign of an older or less reliable roofing system and may require repair. Any non-standard flashings noted during the inspection will be reported below if found.


Roof Covering Materials: Three-tab composition shingle

Approximate Age of Roof Covering: 5-10 Years



Overlay Roof: No

✂️ (RCG-1) Repair: **MISALIGNED SHINGLES/ KICKOUT FLASHING MISSING**

The lower right corner of the roof shows misaligned shingles, which could lead to water runoff issues and increase the risk of water intrusion. Additionally, kickout flashing is needed to direct water into the gutter and prevent damage to the siding/fascia. A professional roofing contractor should assess and address these issues to ensure proper function and durability.



Overall pictures of the roof



Chimneys

Present

Chimney Material: Metal

Chimney Flue Liners: Not visible

Skylights

None noted

Gutters and Downspouts

Gutter and Downspout Materials: Aluminum

Exterior Roofing / Framing

None Noted


Fuel Storage and Distribution

Gas Meter

Present

Gas Shutoff Location: Side of structure

This shows the gas shut ff at the gas meter.



Gas Pipe Materials: Steel and flex pipe


Gas, Propane and Oil Piping

Gas Piping Materials Noted: CSST, Steel



(FSD-2) Repair: IMPROPER USE OF FLEXIBLE GAS CONNECTORS

Flexible gas connectors should not run through the walls of appliances. Use rigid steel pipe only. Have this further evaluated and repaired by a qualified plumber or gas appliance technician.




🔍 (FSD-1) Due Diligence: **NO CSST BONDING FOUND**

The 2009 edition of NFPA 54, National Fuel Gas Code, includes new requirements for special bonding for CSST gas piping systems to the grounding conductor of the building's electrical system to reduce the possibility of damage by lightning strikes by reducing the electrical potential between metallic objects and building systems, including gas distribution. I was unable to locate a bonding connection for the CSST during the inspection today. Have this further evaluated and repaired as recommended by a qualified CSST installer.



- It is possible that bonding is present and was simply not found
- This building pre-dates requirements for bonding so it is more likely the gas piping was never bonded.



Electric Service

Electric Service Voltage Tested

Service Voltage: 120/240

Electric Service

Service Entrance: Below Ground



Meter Base Amperage: 200

Electrical meter



Panel Manufacturer: GE

*AFCI (arc fault protection) is now required on all branch circuits supplying outlets or devices installed in residential dwelling unit kitchens, family rooms, dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreation rooms, closets, hallways, laundry areas, and similar rooms and areas. The goal of this protection is to reduce risks of electrical fires. Consult with a licensed electrician about improving circuit protection as desired. I would consider this improvement in the context of other electrical repairs or upgrades. **Please note that if you add or replace receptacle outlets to the existing system, they should comply with modern AFCI standards.***



I list both of these illustrations to provide a sense of how electrical safety standards change through the years.

Circuits to look for in the panel. Most of these are dedicated except the two kitchen countertop receptacles.

KITCHEN

Refrigerator

Oven/Range

Two kitchen countertop circuits

Dishwasher

Microwave (depends)

Garbage Disposer

LAUNDRY

Washing Machine

Dryer

APPLIANCES



Water heater

AC/heat pump

Electric heaters

Hot Tub/Sauna

Overall pictures of the main electrical panel



Generator Equipment

None noted

Appliance Disconnects

Disconnects Noted: Air Conditioner

Electrical Grounding System

Present - Could Not Confirm

During a home or property inspection, every effort is made to inspect the visible components of the electrical system grounding. The grounding system is critical for safely discharging electrical surges, especially in the case of lightning strikes. There is no way in the context of a home inspection to verify the "effectiveness" of the grounding system as much of the system is not visible, and there are no practical tests one can perform in the way we can test a furnace or a plumbing fixture. However, many things can lead me to recommend further evaluation of the grounding system by a licensed electrical contractor, and they will be documented in the observations below if discovered.

Electrical Bonding System

Present - Could Not Confirm

During the inspection, I attempt to visually document electrical system bonding. There is no way in the context of a home inspection to verify the "effectiveness" of system bonding. All metallic systems in the building are required to be "bonded" (connected) to the the building's electrical grounding system. Bonding creates a pathway to shunt static charges (that would otherwise build up on the system) to earth, and to provide a pathway to trip a breaker in the event that these bonded metallic components became energized. There are many things that can lead me to recommend further evaluation of this system by a licensed electrical contractor and they will be documented as repair items in the observations below if discovered.

Electric Distribution and Finish

Branch Wiring

Wire Material: Copper

Wiring Method: Non-metallic sheathed cable

Receptacles and Fixtures

Inspection Method: Tested All Accessible

During inspection I make an effort to test and inspect all accessible electric receptacles and switches. In general, the scope of testing is directly related to access; where personal belonging and furniture obstruct access to receptacles and fixtures, fewer of them can be reasonably tested during inspection. All defects found during inspection today will be listed in this report. Inspection/

testing of the electrical system can be challenging. It should be anticipated that not all defects will be discovered and that some issues found may actually not be defects at all. Tools used to verify proper wiring and function can vary wildly in reliability/consistency. The kinds of tools that could be used to confidently analyze the system and its function cannot typically be done in the context of a Standard Home Inspection. I look for indications of issues, based on the age of the home, types of wiring systems used etc, as well as personal experience and by testing with a variety of common tools. Issues identified, will be further discussed with recommendations in the electrical section below.

Electric Receptacles: Three wire receptacles

🔧 (EDF-1) Repair: INOPERATIVE LIGHTS

Inoperative lights were found in the basement. Have all inoperative lights further investigated and repaired as needed. If a new bulb does not correct the problem, consult with a licensed electrical contractor.



Basement light fixture

🔧 (EDF-2) Repair: GFCI PROTECTED DEVICE DID NOT TRIP

The GFCI protected receptacle in the kitchen did not respond to testing and may be defective - it did not trip when tested. Have this receptacle repaired or replaced as needed.



Smoke and Carbon Monoxide Alarm Systems

CO Alarms Noted: ☒ On 3rd Floor

CO Alarms: Present

The installation of [carbon monoxide](#) alarms is recommended for all homes that have fuel burning appliances such as gas or oil furnaces, gas water heaters, gas ovens and cooktops, gas fireplaces, and wood stoves. The location should be: **at least one alarm outside of all sleeping areas and one on each floor of the house.** Best practices are to have these alarms hardwired with a battery

back-up - though requirements are for the installation to meet the manufacturer's specifications. Carbon monoxide is a colorless, odorless gas that can cause sickness, nausea, and even death. Alarms have a useful service life of roughly 6 years, so changing them more frequently than smoke alarms is recommended.

Smoke Alarms Noted: ☒ On Main Floor ☒ On 3rd Floor

Smoke Alarms: Present

During a home inspection, a representative sample of smoke alarms is tested using the test button on the alarms. This test does not evaluate the sensor's accuracy; it simply verifies whether the unit is powered. Fire marshals recommend updating smoke alarms every ten years and changing batteries bi-annually to ensure reliability. Current data suggests using photoelectric technology in smoke alarms for enhanced fire detection and to minimize false alarms, which can lead to the disabling of this crucial safety system. Unfortunately, determining whether an alarm uses photoelectric or ionization technology requires removing the unit, and accurately testing a smoke alarm system for reliability, age, and sensor type is surprisingly complex. Many homes have half a dozen or more alarms, further complicating the assessment. A comprehensive evaluation of smoke alarms falls outside the scope of a standard home inspection. For optimal fire safety, it is recommended that homeowners take an active role in understanding, servicing, and maintaining their smoke alarm systems to ensure the safety of all building occupants. [For more information, please read this link.](#)



★ **Inspection Notes:** Carbon monoxide alarms were found and noted during inspection. Be sure to check these regularly. The standard is 1/ floor and 1 outside all sleeping areas.

Ceiling Fans

Ceiling Fans: Present and Tested

The ceiling fans were tested and operating during the inspection. I do not inspect the ceiling fan mounting as this is inaccessible to inspection. It is important the ceiling fans get well-mounted to the ceiling with proper [fan fixture boxes](#).



Ceiling Boxes & Paddle Fans

314.27(C) Boxes at Ceiling-Suspended (Paddle) Fan Outlets. Outlet boxes or outlet box systems used as the sole support of a ceiling-suspended (paddle) fan shall be listed, shall be marked by their manufacturer as suitable for this purpose, and shall not support ceiling-suspended (paddle) fans that weigh more than 70 lb. For outlet boxes or outlet box systems designed to support ceiling-suspended (paddle) fans that weigh more than 35 lb, the required marking shall include the maximum weight to be supported. Outlet boxes mounted in the ceilings of habitable rooms of dwelling occupancies in a location acceptable for the installation of a ceiling-suspended (paddle) fan shall comply with one of the following:

1. Listed for the sole support of ceiling-suspended (paddle) fans
2. An outlet box complying with the applicable requirements of 314.27 and providing access to structural framing capable of supporting a ceiling-suspended (paddle) fan bracket or equivalent

Heating, Cooling, Fireplaces and Ventilation

Heating and Cooling System Overview


HEATING AND COOLING SYSTEM OVERVIEW



Gas furnace exterior



Gas furnace interior



Burners in operation

Heating Systems

Energy Source: Natural gas

Heating Method: Gas forced air furnace

This house has a gas forced air furnace. A critical component to all combustion heating equipment is the heat exchanger. This is the welded metal assembly inside the furnace that contains the products of combustion so that moisture, carbon monoxide and other products of combustion do not mix with interior air and get safely vented to the exterior. Heat exchangers on modern furnaces have an average life expectancy of 15-20 years. Unfortunately, heat exchangers are concealed inside the heating equipment; they are not visible and specifically excluded from a home inspection. Cracks in heat exchangers may be concealed and can pose a potential safety hazard.




This shows an image of a heat exchanger.

Manufacturer: Rheem

Data Plate: 

This shows the data plate from the furnace.



Age: 2018

Listed Max Capacity Per Data Plate: 70,000 btu's

Last Service Record: None

(HCFV-2) Recommended Maintenance: **SERVICE THE HEATING SYSTEM**

Annual servicing of gas forced air furnaces is recommended for safe and reliable heat. I could not find recent service records on the furnace. A servicing is recommended if one has not been done in the last year. The furnace was tested during the inspection and was operational.

Vents and Flues

Present

Air Filters

Filtration Systems: Disposable

The heating and cooling system has disposable air filters installed. These should be changed quarterly or more to ensure proper airflow at the furnace. Be sure to install the filters with the arrows pointing in the same direction as the airflow in the furnace.

✦ Inspection Notes: Filter size: 14x24x1



Heating and Cooling Distribution Systems

Heat Source in Each Room: Present

Distribution Method: Forced Air / Ducts

✦ **Inspection Notes:** Thermal images show approximate temperatures at heating registers. I use these images just to show the system was generally functioning during inspection. These are representative photos.



System Type: Air Source

Listed Nominal Capacity: 2.5 Tons

Energy Source: Electric

Age: 2018

⚠ Limitations:

TOO COLD TO TEST AC

The air conditioning system and condensate control system could not be tested during inspection. Outdoor temperatures should exceed 65 degrees F for at least 24-hours or the air conditioning equipment can be damaged by testing. It is recommended having this system serviced and inspected prior to the next cooling season.



Mechanical Ventilation Systems

Bath Fan Ducting: Ductwork not visible

Determining proper ventilation to the exterior from kitchen, bath, and laundry fans can be tricky as exhaust fan ductwork is often concealed behind finishes and fan terminations can be all over the house from the roof to the foundation, presenting difficulties for systematically checking every fan termination. During inspection, every effort is made to verify proper terminations of fan vents to the exterior, but it is possible to miss something here that is latent or concealed.

Kitchen Fan Ducting: None noted

Gas Fireplaces

Fireplace Types: Fireplace insert

Battery Cradle: Not Applicable

⚠ (HCFV-3) Repair: GAS LOG FIREPLACE SHUT OFF AND IN NEED OF SERVICE

The gas log fireplace was shut off at the time of inspection. I do not like to light these when they are shut off as I do not know why they were shut off and there could be a safety reason. Also, glass pane is foggy. I recommend having this gas log fireplace clean and serviced by a qualified contractor and made operable as needed.



[Website link for gas fireplace owners manuals](#)

Solid Fuel Fireplaces

Fireplace Types: No wood burning fireplaces or appliances noted

Plumbing

Water Meter

Not Found - Inquire With Seller

(P-1) Due Diligence: **NO WATER METER FOUND**

No water meter was found. This house seems to be on a public water system, which should have a metering device. Inquire with the seller or the utility as needed to locate the water meter.

Water Service Supply

Pipe Material: Plastic

Water Supply: Public water

Pressure Reducing Valve: Present

This house has a pressure-reducing valve to control the water pressure. This typically turns the piping system for the building into a closed system. Closed systems require some type of thermal expansion device, typically provided by an expansion tank at the water heater. Though other options exist, such as a Governor 80.



Main Water Shut-off Location: Basement

Main water shutoff valve located behind the clothes washer



Distribution Pipe

Pipe Insulation: Not visible

Supply Pipe Materials: Copper, Only Partly Visible

Copper water supply pipes were installed. Copper pipes installed prior to the late 1980's may be joined with solder that contains lead, which is a known health hazard especially for children. Laws were passed in 1985 prohibiting the use of lead in solder, but prior to that solder normally contained approximately 50% lead. Note that testing for toxic materials such as lead, is beyond the scope of this inspection. Consider having a qualified lab test for lead, and if necessary take steps to reduce or remove lead from the water supply. Various solutions include:

- Flush water taps or faucets. Do not drink water that has been sitting in the plumbing lines for more than 6 hours*
- Install appropriate filters at points of use*
- Use only cold water for cooking and drinking, as hot water dissolves lead more quickly than cold water*
- Have a qualified plumber replace supply pipes and/or plumbing components as necessary*


Functional Flow: Average

Circulation Pump: None Noted

Limitations:

SUPPLY PIPING ONLY PARTLY VISIBLE

Please note that the supply pipes are concealed behind insulation and finishes and visual inspection was limited. Determination of the supply piping materials used here is an educated guess based on the materials that were visible coming out of the wall and below fixtures.



Copper distribution lines

Waste Pipe and Discharge

Discharge Type: Public Sewer - Buyer

Waste and Vent Pipe Materials: PVC

Location of Sewer Cleanout: Basement

This shows the location of the sewer cleanout found during inspection - basement.



Inside the basement closet

(P-2) Due Diligence: VIDEO SEWER SCOPE RECOMMENDED

An evaluation of the sewer line below the ground is beyond the scope of this inspection. A sewer scope is recommended to further evaluate the sewer line and the below ground connections between the house and the municipal sewer line as these are not visible to inspection. Sewer scopes are done using video cameras and can show the materials, condition and reliability of the sewer line. If a video scope has not been done recently, I recommend having a sewer scope performed.

Exterior Hose Bibs

Winterized - not tested

Limitations: WINTERIZED HOSE BIBS

The exterior hose bibs were winterized at the time of inspection and could not be tested. A shut off was found during inspection that is likely for the house bibs.

Additional Sinks

None noted

Sump Pumps and Drains

Floor Drain: Basement Floor Drain Present

A floor drain was noted in the adjacent to the water heater. I do not test floor drains, but I do recommend they be tested for function by the homeowner or a handy person by running a hose in them for a prolonged time or having them professionally scoped by a qualified plumber. The traps in these drains sometimes dry out allowing sewer gases and vermin into the home. As a part of routine maintenance, I recommend making sure the drain trap has water in it and is properly covered.

Sump Pumps: None noted

Sewage Ejector Pumps

Sewage Ejector Pump: None noted

Water Heaters


Water Heater

System Type: Tank

Manufacturer: A.O.Smith

Data Plate: Shown Here

This shows the data plate for this water heater.



Size: 50 gal

Age: 2021

Energy Source: Gas

Straps : None needed - tankless

Pad: None Needed


Drain Pan: Not Needed

Expansion Tank: Present

Relief Valve: Present - Not Tested

A temperature and pressure relief valve (TPRV) is required on all water heaters to discharge any excessive pressure within the tank. A discharge pipe should be attached to the valve and directed to a safe location away from body contact. Newer installations must be directed to the building exterior or to an approved indoor drain receptor. Most manufacturers suggest that homeowners test these valves at least once a year by lifting the lever to ensure the valve discharges properly and also recommend inspection of these safety devices every three years. The picture here shows a typical TPRV. They may also be found on the side of the heater on some models. I do not test these valves due to the possibility that they may leak after testing. A leaking or inoperative TPRV should be replaced immediately by a licensed plumber.

Due to inconsistencies between both UPC and IPC Plumbing codes, and water heater manufacturer's instructions, and TPRV manufacturer instructions, it is not actually possible to install the drain from the Water Heater TPRV "properly." There are conflicts with distance of termination to the floor/ground, types of pipes approved, and diameters of pipes approved. Additional confusion is added when jurisdictional inspectors approve installations/materials specifically not allowed by both codes and manufacturers. My recommendations will vary depending on the installation and will be included in the applicable narratives below.



The arrow shows how a TPRV can be tested

Most codes defer to manufacturer instructions and I favor those recommendations. The yellow tag on the valve states clearly the termination should be 6" above the floor which is more consistent with the UPC code requirements.

Water Temperature

Water Temperature Measured During Inspection: Testing Note, 120 Degrees F



The water temperature was tested multiple times during inspection. It is common for water temperatures to fluctuate throughout the house depending on the distance from the water heater, the water heater settings, the type of water heater and any thermostatic controls used in the plumbing fixtures and mixing valves. For reporting, the median temperature is used.





This thermal image shows approximate water temperature at the time of inspection.



Interior

General Interior Photos







Floors and Floor Materials

Floor Materials: Carpet, Plastic laminate, Tile

Floor Settlement: None noted

Walls, Ceilings, Trim, Hallways and Closets

Wall and Ceiling Materials: Drywall

Wall Insulation and Air Bypass

Wall Insulation: Not Visible

Interior Stairs and Railings


Standard

Interior Doors

Interior Doors: Solid and Hollow Core, Door Adjustment Needed (Door Not Latching (1))

(I-2) Repair: **DOORS NOT LATCHING**

The closet doors to the entrance foyer closet are not latching correctly and requires adjustment so the door latches closed.



Windows

Window Glazing: Single pane

Interior Window Frame: Vinyl

Window Styles: Single hung

Window Brands Noted: Unknown

🔧 (I-3) Repair: **WINDOW REPAIRS/REPLACEMENT NEEDED**

All of the windows in this building are original windows that require maintenance and/or replacement. You need to decide how you want to approach the windows in this building, as they are generally older and do not comply with modern standards for energy efficiency.. Existing windows that have character are often worth preserving and restoring, whereas windows that are in worse condition and have less character may be good candidates for replacement. The windows are in poor condition for age and type.

Examples of observations noted during the inspection include:

- Some windows in the home are not operating and may be painted/sealed shut.
- Missing window hardware was noted
- Condensation noted
- Many of the windows are single pane glass - these older windows do not comply with modern energy efficiency standards





Family room windows are hard to open



Broken tilt latch



Kitchen window sealed shut with caulking



Sealed shut with caulking



Main bedroom windows do not stay open

(I-4) Repair:

LOST SEAL / FAILED INSULATED GLASS UNIT

The exterior front right side window were presenting with a cloudy appearance. Often referred to as a, "lost seal," the cloudy appearance cannot be cleaned. Affected glass typically requires glazing repair or replacement.

Recommendation

Hire a glass replacement company to further evaluate the windows and glass here and replace/update all insulated glass units with lost seals.



- This is a common occurrence in insulated glass, especially as they age and on sun-exposed sides of the building.



Kitchen

General Kitchen Photos



Sinks and Faucets

Tested

No active leaks observed at the time of the inspection.



Cabinets and Countertops

Countertop Material: Unknown

Cabinet Material: Wood laminate

(K-3) Repair: **CABINET DRAWER IN CONFLICT**

A kitchen cabinet drawer adjustment is needed for proper operation of the kitchen cabinet as is in conflict with the dishwasher.



(This video is only viewable online.)

Disposers

Disposer: Operated

Dishwasher

Dishwasher: Not Operated

Though kitchen appliances are generally beyond the scope of a home inspection, I was unable to run the dishwasher as it was being used. No signs of leakage or water damage were visible. It is always wise to monitor the dishwasher after moving in.



Ventilation Method

Fan Above Cooktop

Ranges, Ovens and Cooktops

Range/ Oven /Cook-tops: Gas

The oven and cooktop were tested during the inspection and were operable. Ovens are tested in bake mode only. Appliances are generally beyond the scope of a home inspection but are tested for basic function as a courtesy. This does not include testing to see if the thermostat is accurate, for example.



Refrigerators

Refrigerator: Operating, Operating with IR, Filter Noted

Q (K-6) Due Diligence: REFRIGERATOR FILTER NOTED

The refrigerator water / ice system seems to employ a filter. Inquire with the seller for additional information regarding replacement schedule and the types of filters needed.

Thermal images show the freezer and refrigerator working during the inspection.



General Kitchen Condition

Standard

Laundry Facilities

Washer

Not tested (Clothes in washer)

Limitations:

CLOTHES WASHER NOT TESTED

The clothes washer was not tested today as clothes were present in the appliance.



Dryer

Tested

Proper dryer exhaust venting is critical for safe and reliable performance from the dryer. Here are some basic rules of thumb for dryer [exhaust duct installation](#): Unless a vent-free appliance is being used, the dryer exhaust vent must terminate outdoors. It should be no more than 25 feet long and for every 90 degree turn subtract 5 feet and for every 45 degree bend subtract 2.5 feet. Use only smooth-wall metal vent pipe @ 4 inch pipe diameter. Do not use plastic pipe and plastic flex pipe. If a flexible connector is needed behind the dryer use a short amount of corrugated metal pipe. If the exhaust duct is getting pinched behind dryer, consider use of a dryer vent box, pictured here. Flex and corrugated pipes should never be used in concealed spaces such as through walls or in attic or crawl spaces. Insulate dryer exhaust duct where it passes through unconditioned spaces to prevent condensation that could hasten lint build-up inside the pipe. Do not use screws to connect pipe as these can trap lint. Secure duct with foil tape as needed. Be sure duct is sleeved properly so that it will not trap lint and clean the vent regularly, especially if it is a long exhaust run.



This shows an example of a dryer vent box

Power Source: Not visible

Exhaust Duct: Ducted to Exterior

(LF-1) Repair:

SCREENED DRYER EXHAUST VENT COVER

The [dryer exhaust duct](#) termination at the exterior of the building is covered with a screen. This is a potential safety hazard that could block lint and cause a fire. Replace this vent cover with a cover that has a backdraft damper.



Thermal image shows the dryer was tested and operating at the time of inspection.



Laundry Sinks

None noted

Bathrooms

General Bathroom Photos

Overall Bathroom pictures



Sinks and Cabinets

Tested

(B-2) Repair: **SLOW SINK DRAIN**

A slow drain was noted at the basement bath sink. Repair as needed so the drain keeps up with the fixture supply.

- This often involves just cleaning out the trap.



Basement bathroom sink

Toilet

Tested

Bathtub / Shower

Tested

Shower Type: Tile

Tub Type: Acrylic/Fiberglass

(B-3) Repair: **SLOW TUB DRAIN**

The main bath bathtub drain is slow and appears to be obstructed. Repair as needed for reliable drainage.



Main bathroom tub

Bathroom Ventilation

Type: Bath fan

General Bath

Standard

Inspection Notes: BATHROOM TESTING PROCEDURES

During inspection today I operated all plumbing fixtures in bathrooms. I ran a moisture meter around toilets and tile shower enclosures to check for concealed leaks and sounded for loose tile and finishes in shower and tub enclosures. I do not test bathtub overflow drains as this risks damaging finishes around the tub. **Monitor tubs while filling and avoid pushing water into the overflow. Even well-installed overflow drains can leak as the gaskets that seal the overflow will dry out over time and may no longer provide a watertight seal.** Monitor plumbing after moving into a new home as testing during inspection presents less stress on plumbing than daily use. Please note that vacant homes present additional risk as it can be difficult to distinguish how the plumbing system will respond to daily use. Any defects uncovered during inspection are listed in this report.

After running water on bathroom fixtures, no leaks were detected.



Attic

Attic Access

, Walked

This shows the location of the attic access in the: MAIN BEDROOM CLOSET



Attic Pulldown Ladders

None Noted

Roof Framing and Sheathing

Rafters: Truss

Sheathing: OSB

(A-1) Monitor: **OLD STAINED NOTED**

A stain was observed on the FRT plywood around the chimney flue, indicating a past moisture issue. No active moisture was detected on the insulation, suggesting the issue has been resolved. It is recommended to inspect the chimney flashing and monitor the area periodically to ensure no recurrence.



Pictures of roof structure



Fire Separation and Fire Blocking

Fire Blocking and Fire Separation in Attic: Not Fully Visible

Attic Insulation

Insulation Type: Fiberglass, Batt Insulation

Approximate Insulation R-Value on Attic Floor: Inconsistent

Approximate Insulation R-Value on Attic Ceiling: Not needed

Approximate Insulation R-Value on Attic Walls: Not applicable

(A-2) Repair: **BAFFLES NOT INSTALLED**

Cardboard baffles have not been installed in the rafters near the eaves in the attic. This has allowed the fiberglass batt insulation to block ventilation from the soffit. This can inhibit proper ventilation of this roof cavity and can lead to heat build-up and seasonal moisture problems. It is recommended removing insulation away from the roof decking in these areas as is possible - this will be difficult work due to the tight space restrictions. Where possible baffles should be added though this could be difficult at this point.



(A-3) Repair: **ATTIC INSULATION ADJUSTEMENT RECOMMENDED**

Localized tune-up repairs are needed to the attic insulation to ensure reliable performance. During inspection the following observations were noted:



- Blown in insulation has been disturbed by contractors or prior attic access



Attic Fan Exhaust Vents

 **Inspection Notes:** The accessible exhaust fan vents in the attic were noted to be correctly terminating to the exterior where visible.

Attic and Roof Cavity Ventilation

Attic Ventilation Method: Soffit vents

Attic and roof cavity ventilation is a frequently misunderstood element of residential construction. All roof cavities are required to have ventilation. The general default standard is 1 to 150 of the attic area and ideally, this comes from at least 60% lower roof cavity ventilation and 40% upper, but this is an over-simplifications of the subject. As a good guiding principle the most important elements for healthy attic spaces, which are traditionally insulated and ventilated are:

1. **Make sure the ceiling between the living space and the attic is airtight**
2. *Ventilate consistently across the whole lower part of the roof cavity with low, intake soffit venting*

3. Upper roof cavity venting is less important and if over-installed can exacerbate air migration into the attic from the living space.
4. Avoid power ventilators which can depressurize the attic and exacerbate air migration from the house into the attic.

For more information, please see: [Link](#)

Structure and Basement

Foundation

% of Foundation Not Visible: 90%

Building Configuration: Basement

Foundation Description: Poured concrete

Floor, Wall and Ceiling Framing

Wall Framing: Partly visible, 2x4

Wall Sheathing: Not visible

Floor Framing: Partly visible, 2x8

Sub-Floor Material: Plywood

Ceiling Framing: Not visible

Basement

Finished

Basement Moisture

None noted

★ Inspection Notes:

NO SIGNS OF BASEMENT MOISTURE WERE FOUND

I inspected all around the basement for signs of moisture and / or moisture control problems. No water stains, or damaged baseboard were noted and no signs of paint touch up near the floor. Basement did not smell musty at the time of inspection and seems to be performing well to date.



Dry at the time of the inspection

Checking Out Procedure

Check Out List

Oven: ☒ Off

Lights: ☒ Off

Heating and Cooling: ☒ Restored to Pre-inspection temperatures

Appliances: ☒ Off / finishing cycle



Home Inspections DMV, LLC

301-250-3711

www.inspectionsDMV.com

contact@inspectionsdmv.com

Inspected by:

Heriberto Interiano

MD, D.C & VA State Inspector License No. MD 34937, VA 3380002208

